

Remove Defect

Wet Use Sanding	
G Sand Denibbing	GSD320
Rose P2000	
G Sand Denibbing	GSA301
Block	
G Sand Waterproof	GSW115
Half Sheets P1500	
G Sand Waterproof	GSW120
Half Sheets P2000	
G Sand Flatting Block	GSA012

Dry Use Sanding

G Sand 75mm Abrasive	GSD712
Film Discs P1200	
G Sand 75mm Abrasive	GSD715
Film Discs P1500	
G Sand 75mm Abrasive	GSD720
Film Discs P2000	
G Sand 75mm Abrasive	GS3701
Foam Discs P3000	
G Sand 150mm Abrasive	GSD112
Film Discs P1200	
G Sand 150mm Abrasive	GSD115
Film Discs P1500	
G Sand 150mm Abrasive	GSD120
Film Discs P2000	
G Sand 150mm Abrasive	GS3101
Foam Discs P3000	
G Sand 150mm	GSA106
Interface Pad	

Prod 500g 1kg	luct Size	Codes G3U501 G3U130	Proc 500g 1kg 1 US
G Mop 6" Yellow (Compounding Foa Compounding Foa Compounding Foa	m GMC612	Applicators G Mop 3" Finishin G Mop 6" Finishin G Mop 8" Finishin
ATTACH Attach a G Mop Yellow Compound- ing Foam to a polishing machine	Shake bottle well before use	Dispense a small quantity of product onto surface or pad	Attach a G Mop Finishing Foam to a polishing machine
4 1500 - 1800fpm Compound at 1500 - 1800fpm	Wipe clean with a Enishing Cloth FC-3 (3 x cloths)	Tip: Prior to first use of a new pad, roughen with a Spurring Brush (1090005) to ensure optimum results. Clean pad with the Spurring Brush after use.	Spread and start compounding at 1000rpm

Stage 1: CUT

2. Finishi	ng	
	E,	
	G3 Fine Finishing Compound	Stage 2: FINISH



G3 Ultra System Process Chart

ng Foam ng Foam ng Foam



before use

Dispense a small quantity of product onto surface or pad



Slowly increase

Wipe clean with a Finishina Cloth

FC-3 (3 x cloths)



ottle well	Rub the proc
ply a small	a circular ma
/ to the	onto the surf
	with a cloth

roduct in Allow to dry to a haze



ATTACH		1000 - 1500rpm	\neg
Attach a G Mop Finishing Foam to a machine	Shake bottle well and apply a small quantity to pad or surface	Compound at 1000 - 1500rpm	Wipe clean Finishing Clo FC-3 (3 x clo
G3 Wax - Primary A	pplication by hand		
		3	
Shake bette well	Dub the product in	Allow to dry to a	Wino cloan





Farécia 63 Ap G G G

G3 Ultra

Compound

Premium Abrasive

For High & Ultra High Solids Paint Systems

1. Compounding



speed to 2000rpm. DO NOT ALLOW PRODUCT TO DRY

Codes

G3F501

G3F101

G3F118

Codes

GMF301

GMF601

GMF801

Shake b

3. Protecting

Farécia 63 GLAZT



OR

Codes

G3G501

G3G101

G3 Glaze

Gloss Enhancer

Product Size

1 US gallon

G3 Glaze - Primary Application by machine

500ml

Applicators for both products

G Mop 3" Finishing Foam

G Mop 6" Finishing Foam

G Mop 8" Finishing Foam

Finishing Cloth (3 x cloths)

t ATTACH

1 ltr

G3 Wax

Premium Liquid

Product Size Codes

500ml

1 ltr

G3G118 1 US gallon

Protection

G3W501

G3W106

G3W118

LIT1786 (V2 06-2015)

Farécia G3 WAX

Codes

GMF301

GMF601